

Bradenhead Re-Test Form

Use this form to document all re-test information. Please enter in all information using N/A where appropriate.

Well Information	
Well Name & Number:	28-7 186
API:	3003920640000
Section:	28-7 186
Township:	San Juan
Range:	

Test Information	
Date of Re-Test:	8/18/10
Well Status: Prod ~ SI ~ TA	flowing
Initial Pressures	
TBG:167	INT:353
CSG: 353	BH: 0

RCVD AUG 20 '10
OIL CONS. DIV.
DIST. 3

BRADENHEAD

Test Time	BH	CSG	INT
5 minutes:	0	353	353
10 minutes:	0	353	353
15 minutes:	0	353	353
20 minutes:	0	353	353
25 minutes:			
30 minutes:			

Intermediate

INT	CSG
28	353
0	353
0	353
0	352
0	352
0	352

End of Test 5 minute SI:	0		
--------------------------	---	--	--

7	
---	--

Flow Characteristics	BH	INT
Steady Flow:		
Bubbles:		
Flow to Nothing:		x
No Flow:	x	
Gas:		x
Water:		
Gas & Water:		

9

Water Flow	
Clear	
Fresh	
Salty	
Sulfur	
Black	
Muddy	

MSO Comments/Info		
yearly BH test. Chondra		
Tested By: Pat Stawinski	Company (BR or COP): COP	Witness: NO