



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/19/10 Operator Energen Resources API # 3003922286

Property Name CARSON 3 Location: Unit N Section 30 Township 30 Range 4  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 220 Intermediate 0 Casing 230 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	No Blow	230	<del>230</del> 0	No Blow	235			
10 minutes	No Blow	235	<del>235</del> 0	No Blow	235			
15 minutes	No Blow	235	<del>235</del> 0	No Blow	240			
20 minutes								
25 minutes								
30 minutes								
5 minute SI								

Steady Flow		
Surges		
Down to Nothing		
No Flow	X	X
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_

5 Minute Shut-in Bradenhead 0 Intermediate 0

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By [Signature]  
Ruiz  
(Position)

Witness \_\_\_\_\_

