

50532/9207

Benson-Montlin-Greer

03:37:34 p.m. 07-20-2010

1/1



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6170 FAX: (505) 334-6170
<http://omnr.state.nm.us/ocd/District/10361etrio.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/22/10 Operator Benson Montlin Greer API #30-0 39-22592

Property Name EPCMU Well No. 40 Location: Unit E Section 19 Township 27N Range 1E

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 44 Casing 50 Bradenhead 21
Injection well

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Testing	PRESSURE			FLOW CHARACTERISTICS		
	Bradenhead	INTERM		BRADENHEAD	INTERMEDIATE	
	BH	Int	Csg	Int	Csg	
TIME						
5 min	<u>0</u>		<u>50</u>			Steady Flow
10 min	<u>0</u>		<u>50</u>			Surges
15 min	<u>0</u>		<u>50</u>			Down to Nothing <u>X</u>
20 min						Nothing
25 min						Gas <u>X</u>
30 min						Gas & Water
						Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: Down to Oppt in 20 sec.



By Ben L. Greer

Witness

(Position)

E-mail address