



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 8/1/10 Operator Energien Resources API # 3003922779

Property Name CHICOSA CANYON 1 Location: Unit M Section 35 Township 31 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 0 Intermediate N/A Casing 40 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>No flow</u>	<u>40</u>	<u>N/A</u>	<u>N/A</u>		Steady Flow		
10 minutes	<u>No flow</u>	<u>40</u>	<u>N/A</u>	<u>N/A</u>		Surges		
15 minutes	<u>No flow</u>	<u>40</u>	<u>N/A</u>	<u>N/A</u>		Down to Nothing		
20 minutes						No Flow	<u>X</u>	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

By

[Signature]
Purveyor

(Position)

Witness

