

5053279207

Benson-Montin-Greer

03:37:34 p.m. 07-20-2010



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (800) 334-6170
<http://aimnrd.state.nm.us/ocod/District/INUSdistrio.html>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/29/10 Operator Benson Montin Greer API #30-0 39-22814

Property Name COU Well No. 21 Location: Unit 3 Section 32 Township 24N Range 1W

Well Status (Shut-In or Producing) Initial PSI: Tubing 30 Intermediate 1/4 Casing 30 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

By Bent L. Gonzalez

Witness _____

(Position)

E-mail address _____

