



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test: 7-12-10 Operator: RESOURCE DEVELOPMENT TECHNOLOGY, LLC API #30-039-22903

Property Name: CLU Well No. 314 Location: Unit J Section 21 Township 25N Range 6W

Well Status: (Shut-In or Producing) Initial PSI: 300 Intermediate: NA Casing: 310 Bradenhead: 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

Testing Time	Bradenhead			Intermediate			Bradenhead		Intermediate
	BH	Int	Csg	Int	Csg		Flowed	Flowed	
5 Min	<u>0</u>	NA	<u>310</u>	NA	NA	Steady Flow			NA
10 Min	<u>0</u>	NA	<u>310</u>	NA	NA	Surges			NA
15 Min	<u>0</u>	NA	<u>310</u>	NA	NA	Down to Nothing			NA
20 Min	<u>0</u>	NA	<u>310</u>	NA	NA	Nothing	<u>X</u>		NA
25 Min	<u>0</u>	NA	<u>310</u>	NA	NA	Gas			NA
30 Min	<u>0</u>	NA	<u>310</u>	NA	NA	Gas & Water			NA
						Water			NA

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE: NA

REMARKS:

Nothing - 1st shut - BH
Good

By: Art Sullivan

Witness _____

Lease Operator -- Pumper
(Position)

E-mail address: lizard3s@wildblue.net

