

5053279207

Benson-Montlin-Greer

03:37:34 p.m.

07-20-2010

1/1



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
 AZTEC DISTRICT OFFICE
 1000 RIO BRAZOS ROAD
 AZTEC NM 87410
 (505) 334-0170 FAX: (505) 334-0170
<http://omnr.state.nm.us/ocd/District/IV3/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/22/10 Operator Benson Montlin Greer API #30-0 39-23209

Property Name EPCMU Well No. 37 Location: Unit C Section 8 Township 26N Range 1E

Well Status (Shut-In or Producing) Initial PSI: Tubing 64 Intermediate 11 Casing 26 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min						Steady Flow	
10 min						Surges	
15 min						Down to Nothing	
20 min						Nothing	<u>X</u>
25 min						Gas	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD _____

INTERMEDIATE _____

REMARKS:

By Ben P. Herfolds

Witness _____

(Position)

E-mail address _____

