



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-26-10 Operator Elm Ridge Exploration API # 30-039-23365


Property Name Martin Whittaker Well No. 21 Location: Unit I Section 7 Township 23 Range 4

Well Status (Shut-In or Producing) Initial PSI: Tubing 170 Intermediate NA Casing 180 Bradenhead 6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>NA</u>	<u>180</u>		
10 min	<u>0</u>	<u>NA</u>	<u>180</u>		
15 min	<u>0</u>	<u>NA</u>	<u>181</u>		
20 min	<u>0</u>	<u>NA</u>	<u>181</u>		
25 min	<u>0</u>	<u>NA</u>	<u>181</u>		
30 min	<u>0</u>	<u>NA</u>	<u>182</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>X</u>
Nothing	
Gas	
Gas & Water	
Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

BRADENHEAD Blew Down To Nothing After 5 min There was
Nothing on BRADENHEAD

By Ronald Graves

Witness _____

Pumper
(Position)

E-mail address _____