

5053279207

Benson-Monlin-Greer

03.37.34 p.m.

07-20-2010



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-8178 FAX: (505) 334-8170
<http://emrmd.state.nm.us/ood/Districts/11/aztecdists.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/28/10 Operator Benson Monlin Greer API #30-0 39-24100Property Name COU Well No. 36 Location: Unit A Section 20 Township 25N Range 1WWell Status (Shut-In or Producing) Initial PSI: Tubing 19 Intermediate 4 1/2 Casing 19 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>X</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK 5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS:

By Benson Monlin GreerWitness

(Position)

E-mail address 