

5053279207

Benson-Montin-Greer

03:37:34 p.m.

07-20-2010

1/1



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(805) 384-0170 FAX: (805) 384-0170
<http://oilconservation.state.nm.us/aztec/District%20Office.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/29/10 Operator Benson Montin Greer API #30-0 39-24173Property Name CDU Well No. 38 Location: Unit F Section 7 Township 25N Range 1WWell Status (Shut-In or Producing) Initial PSI: Tubing 31 Intermediate N/A Casing 31 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		31		31
10 min	0		31		31
15 min	0		31		31
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

Steady Flow

Surges


Down to Nothing

Nothing

Gas

Gas & Water

Water



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE _____

REMARKS:

Down to Nothing in 20 sec.

By

Benson Montin Greer

Witness

(Position)

E-mail address