



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-3-2010 Operator Energen Resources API # 3003924279 ✓
Property Name Carrocas Unit 27 A #14 Location: Unit N Section 27 Township 32N Range 5W
(Well Name and Number)
Pressure (Shut-in or Producing) Tubing 65 Intermediate NA Casing 98 Bradenhead 10

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	98				Steady Flow	
10 minutes	0	98				Surges	
15 minutes	0	98				Down to Nothing	X
20 minutes	0	98				No Flow	X
25 minutes	0	98				Gas	
30 minutes	0	98				Gas and Water	
5 minute SI	0	98				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS: BH had 10 psig upon arrival - Puffed when valve was opened,
then nothing. NO recordable pressures or blow downs were
seen.

By Jon Nobis Witness _____
Lease operator
(Position)