



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/23/10 Operator Energen Resources API # 3003924328

Property Name SAN JUAN 32 5 UT NP 107 Location: Unit H Section 26 Township 32 Range 6

(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 80 Intermediate Casing 80 Bradenhead

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>80</u>	<u>N/A</u>	<u>N/A</u>		Steady Flow	
10 minutes	<u>0</u>	<u>80</u>				Surges	
15 minutes	<u>0</u>	<u>80</u>				Down to Nothing	
20 minutes						No Flow	<u>/</u> <u>N/A</u>
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

By Alan Kirk

Witness

Senior Lease Operator

(Position)

