



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/25/10 Operator Energen Resources API # 3003924336

Property Name CARRACAS UNIT 16 B 6 Location: Unit F Section 16 Township 32 Range 4  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 80 Intermediate N/A Casing 41 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	41	N/A			Steady Flow	
10 minutes	0	41				Surges	
15 minutes	0	41				Down to Nothing	
20 minutes	0	41				No Flow	X N/A
25 minutes	0	41				Gas	
30 minutes	0	41				Gas and Water	
5 minute SI	0	55				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

By [Signature]  
Lease Operator III  
(Position)

Witness \_\_\_\_\_

