



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-23-2010 Operator Energex Resources API # 3003924349

Property Name CARRACAS UNIT FR 102 Location: Unit 1 Section 11 Township 32 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 300# Intermediate 1/A Casing 0# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0#</u>	<u>0#</u>	<u>1/A</u>	<u>1/A</u>	<u>1/A</u>		
10 minutes	<u>0</u>	<u>0</u>					
15 minutes	<u>0</u>	<u>0</u>					
20 minutes	<u>0</u>	<u>0</u>					
25 minutes	<u>0</u>	<u>0</u>					
30 minutes	<u>0</u>	<u>0</u>					
5 minute SI	<u>0#</u>	<u>0#</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>		
						Steady Flow	
						Surges	
						Down to Nothing	
						No Flow	<u>✓</u>
						Gas	
						Gas and Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0# Intermediate 1/A

REMARKS:

Well is POW



By Michael Howe

Witness _____

Sr. Lease Operator
(Position)