



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-25-2010 Operator Energen Resources API # 3003924412

Property Name CARRACAS UNIT 22 A 13 Location: Unit M Section 22 Township 32 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 65 Intermediate Casing 138 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead Intermediate		
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed	
5 minutes	<u>0</u>	<u>138</u>				Steady Flow	<u>NO</u>		
10 minutes	<u>0</u>	<u>138</u>				Surges	<u>NO</u>		
15 minutes	<u>0</u>	<u>139</u>				Down to Nothing	<u>NO</u>		
20 minutes	<u>0</u>	<u>139</u>				No Flow	<u>NO</u>		
25 minutes	<u>0</u>	<u>138</u>				Gas	<u>NO</u>		
30 minutes	<u>0</u>	<u>138</u>				Gas and Water	<u>NO</u>		
5 minute SI	<u>0</u>	<u>139</u>				Water	<u>NO</u>		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear NA Fresh NA Salty NA Sulfur NA Black 214

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:


was 0 on Bradenhead from the beginning
to the end of the test

By

[Signature]
lease operator

(Position)

Witness



NMOCD Test Area: C

62