



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/9/10 Operator Jon Nobis API #30-03924424

Property Name Cartacas unit Well No 21 A#15 Location: Unit 0 Section 21 Township 32N Range 5W

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate X Casing 0 Bradenhead under 1 psi

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	N/A	0		
10 min	0	N/A	0		
15 min	0	N/A	0		
20 min	0	N/A	0		
25 min	0	N/A	0		
30 min	0	N/A	0		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>0</u>	<u>NA</u>
Surges	<u>0</u>	<u>NA</u>
Down to Nothing	<u>0</u>	<u>NA</u>
Nothing	<u>X</u>	<u>NA</u>
Gas	<u>0</u>	<u>NA</u>
Gas & Water	<u>0</u>	<u>NA</u>
Water	<u>0</u>	<u>NA</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

BH had less than 1 psi on arrival - opened valve and
Had an almost inaudible puff. No pressure or volume was
noticed during the remainder of the test. Well POW

By Dillon Gage

Witness _____

Field Foreman
(Position)

E-mail address dillon.gage@energy.com

