



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-12-2010 Operator Energen Resources API # 3003924443

Property Name CARRACAS UNIT FR 110 Location: Unit P Section 26 Township 32 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 63* Intermediate N/A Casing 90* Bradenhead 0*

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0*</u>	<u>90*</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	<u>Steady Flow</u>	
10 minutes	<u>0</u>	<u>90</u>				Surges	
15 minutes	<u>0</u>	<u>90</u>				Down to Nothing	
20 minutes	<u>0</u>	<u>90</u>				No Flow	<u>✓</u>
25 minutes	<u>0</u>	<u>90</u>				Gas	
30 minutes	<u>0</u>	<u>90</u>				Gas and Water	
5 minute SI	<u>0*</u>	<u>115*</u>	<u>✓</u>	<u>✓</u>	<u>✓</u>	Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0* Intermediate N/A

REMARKS:

By Michael Howe Witness
Sr. Lease Operator
(Position)

