



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/25/10 Operator Energen Resources API # 3003924718

Property Name CARRACAS UNIT 15 B 14 Location: Unit N Section 15 Township 32 Range 4  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 5 Intermediate N/A Casing 42 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	0	42	N/A			Steady Flow	
10 minutes	0	42				Surges	
15 minutes	0	42				Down to Nothing	
20 minutes	0	42				No Flow	X N/A
25 minutes	0	42				Gas	
30 minutes	0	42				Gas and Water	
5 minute SI	0	45				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:



By [Signature] Witness \_\_\_\_\_  
Lease Operator III  
(Position)