



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-22-2010 Operator Energen Resources API # 3003925332

Property Name CARRACAS UT PC 35 B 8 Location: Unit H Section 35 Township 32 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 60# Intermediate 1A Casing 90# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate Flowed Flowed	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0#</u>	<u>90#</u>	<u>1A</u>	<u>1A</u>	<u>1A</u>	Steady Flow	
10 minutes	<u>0</u>	<u>90</u>				Surges	
15 minutes	<u>0</u>	<u>90</u>				Down to Nothing	
20 minutes	<u>0</u>	<u>90</u>				No Flow	<input checked="" type="checkbox"/>
25 minutes	<u>0</u>	<u>90</u>				Gas	
30 minutes	<u>0</u>	<u>90</u>				Gas and Water	
5 minute SI	<u>0#</u>	<u>10#</u>	<u>✓</u>	<u>✓</u>	<u>✓</u>	Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0# Intermediate 1A

REMARKS:

By Michael Howe Witness
Sr. Lease Operator
(Position)

