



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/21/10 Operator Energen Resources API # 3003926364

Property Name SAN JUAN 32 5 UNIT 19 Location: Unit N Section 23 Township 32 Range 6
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 165 Intermediate N/A Casing 170 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>170</u>	<u>N/A</u>	<u>N/A</u>			
10 minutes	<u>0</u>	<u>170</u>					
15 minutes	<u>0</u>	<u>170</u>					
20 minutes							
25 minutes							
30 minutes							
5 minute SI							
						Steady Flow	
						Surges	
						Down to Nothing	
						No Flow	<u>N/A</u>
						Gas	
						Gas and Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

By Alan Kirk Witness _____
Senior Lease Operator
(Position)

