



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX. (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/24/10 Operator Energen Resources API # 3003926485

Property Name CARRACAS 17 B 14 Location: Unit N Section 17 Township 32 Range 4
(Well Name and Number)

Pressure (Shut-in) or Producing) Tubing Intermediate N/A Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0	0				Steady Flow		
10 minutes	0	0				Surges		
15 minutes	0	0				Down to Nothing		
20 minutes	0	0				No Flow	X	N/A
25 minutes	0	0				Gas		
30 minutes	0	0				Gas and Water		
5 minute SI						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

Well POW

By [Signature]
Lease Operator III
(Position)

Witness

