



**NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/26/10 Operator Energen Resources API # 3003926623

Property Name SAN JUAN 32 5 UNIT 11B Location: Unit 0 Section 23 Township 32 Range 6
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 142 Intermediate N/A Casing 145 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes	0	145	N/A	N/A								
10 minutes	0	145										
15 minutes	0	145										
20 minutes												
25 minutes												
30 minutes												
5 minute SI												

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____

5 Minute Shut-in Bradenhead 0 Intermediate N/A



REMARKS:

By Alan Kirk
Senior Lease Operator
(Position)

Witness _____