



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/7/10 Operator Energen Resources API # 3003926654

Property Name SAN JUAN 30 4 UNIT 51 Location: Unit 0 Section 27 Township 30 Range 4
(Well Name and Number)

Pressure Shut-in or Producing) Tubing 170 Intermediate N/A Casing 190 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	<u>No blow</u>	<u>195</u>	<u>N/A</u>	<u>N/A</u>		Steady Flow	
10 minutes	<u>No blow</u>	<u>200</u>	<u>N/A</u>	<u>N/A</u>		Surges	
15 minutes	<u>No blow</u>	<u>205</u>	<u>N/A</u>	<u>N/A</u>		Down to Nothing	
20 minutes						No Flow	<u>X</u>
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

Bradenhead Had Nothing

By

Don Del
Pumper

(Position)

Witness

