



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX. (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/30/10 Operator Energen Resources API # 3003927269

Property Name SAN JUAN 32 5 UNIT 103S Location: Unit P Section 24 Township 32 Range 6
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 140 Intermediate N/A Casing 140 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>140</u>	<u>N/A</u>	<u>N/A</u>		Steady Flow		
10 minutes	<u>0</u>	<u>140</u>				Surges		
15 minutes	<u>0</u>	<u>140</u>				Down to Nothing		
20 minutes						No Flow	<u>/</u>	<u>N/A</u>
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

By Alan Kirk
Senior Lease Operator
(Position)

Witness _____

