

## **NEW MEXICO ENERGY, MINERALS** AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

## **BRADENHEAD TEST REPORT**

			(Submi	t 2 copies to at	ove addre	ess)		
-		Operator —	Energen Resources			API# 30	03927456	
		CYN UT 26B 7	Locatio	Location: Unit G Section 26		ownship 32	32 Range 4	
		(Well Name	e and Number)		,	(a		
Pressure (Sh	ut-in or Proc	ducing	Tubing	72 Interme	diate <u>//</u>	Casing 9	8 Braden	nead 🕏
OPEN	N BRADENH	EAD AND	INTERMEDIA	TE TO ATMOSI	PHERE INC	DIVIDUALLY FOR	15 MINUTES	EACH
	Bradenhead			Interme	diate	]	Bradenhead	Intermediate
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0	98				Steady Flow		<u> </u>
10 minutes	0	98				Surges		
15 minutes	0	98				Down to Nothing		
20 minutes	0	98				No Flow		
25 minutes	0	98				Gas		
30 minutes	0	98				Gas and Water Water		
5 minute SI	0	102				Vvater		
<u>If bradenhe</u>	ead flowed v	water, ch	eck all of the d	escriptions tha	t apply bel	low:		
Clear	F	resh _	Sal	ty	Sulfur	Bla	101112131475	
= =4140	had in D		<i>(</i> ^)	lata mana diat	VA	(A)		OLIE!
5 Minute S	nut-in B	tradenhea	Id	Intermediat	////	456	RECEIVE	0 8 920
REMARKS:	•					8	AUG 2010 OIL CONS. DIV. DIST	20212
						1/4		
							SE 82 LZ 97.5	t <sup>40</sup>
111	1/2							
By ///	or Operal			Wi	tness			
1 hzas	se Operal	VIII	-					

(Position)