



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-1-2010 Operator Energen Resources API # 3003927548

Property Name CARRACAS 24 A 12 Location: Unit L Section 24 Township 32 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 520 Intermediate Casing 520 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead Intermediate		
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed	
5 minutes	0	50				Steady Flow	NO		
10 minutes	0	50				Surges	NO		
15 minutes	0	52				Down to Nothing	NA		
20 minutes	0	52				No Flow	NO		
25 minutes	0	50				Gas	NO		
30 minutes	0	52				Gas and Water	NO		
5 minute SI	0	52				Water	NO		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

through the hole test

By [Signature]
Lease operator
(Position)

Witness

