



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)


Date of Test 7/12/10 Operator Energen Resources API # 30-03927557

Property Name Carson Well No. 13A Location: Unit L Section 32 Township 30 Range 4

Well Status (Shut-In or Producing) Tubing O Intermediate N/A Casing 140 Bradenhead O

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING	FLOWED	FLOWED
5 minutes	<u>No flow</u>	<u>N/A</u>	<u>140</u>	Steady Flow	
10 minutes	<u>No flow</u>	<u>N/A</u>	<u>140</u>	Surges	
15 minutes	<u>No flow</u>	<u>N/A</u>	<u>140</u>	Down to Nothing	
20 minutes				Nothing <u>X</u>	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE N/A

REMARKS:

Braden had Nothing

By [Signature] Witness _____

(Position)