



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-25-2010 Operator Energen Resources API # 3003927564

Property Name CARRACAS 19 B 11 Location: Unit K Section 19 Township 32 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 26 Intermediate Casing 48 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	<u>0</u>	<u>48</u>				Steady Flow	<u>NO</u>
10 minutes	<u>0</u>	<u>47</u>				Surges	<u>NO</u>
15 minutes	<u>0</u>	<u>48</u>				Down to Nothing	<u>NO</u>
20 minutes	<u>0</u>	<u>47</u>				No Flow	<u>NO</u>
25 minutes	<u>0</u>	<u>47</u>				Gas	<u>NO</u>
30 minutes	<u>0</u>	<u>48</u>				Gas and Water	<u>NO</u>
5 minute SI	<u>0</u>	<u>48</u>				Water	<u>NO</u>

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

0 on Bradenhead from the Beginning to the end
of test

By

[Signature]
Lease operator
(Position)

Witness

