



# NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

## BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-3-2010 Operator Energex Resources API # 3003927660

Property Name CARRACAS 27 A 3 Location: Unit C Section 27 Township 32 Range 5  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 58 Intermediate        Casing 109 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead Intermediate		
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed	
5 minutes	0	109				Steady Flow	no		
10 minutes	0	109				Surges	no		
15 minutes	0	109				Down to Nothing	NA		
20 minutes	0	108				No Flow	no		
25 minutes	0	109				Gas	no		
30 minutes	0	109				Gas and Water	no		
5 minute SI	0	109				Water	no		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear NA Fresh NA Salty NA Sulfur NA Black NA

5 Minute Shut-in Bradenhead 0 Intermediate       

REMARKS: 0 through the hole test

By [Signature]  
Lease operator  
(Position)

Witness       

