



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-1-2010 Operator Energen Resources API # 3003929821

Property Name CARRACAS 26 A 11 Location: Unit I Section 27 Township 32 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 210 Intermediate 210 Casing 200 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead Intermediate		
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed	
5 minutes	<u>0</u>	<u>200</u>				Steady Flow	<u>NA</u>		
10 minutes	<u>0</u>	<u>200</u>				Surges	<u>NA</u>		
15 minutes	<u>0</u>	<u>200</u>				Down to Nothing	<u>NA</u>		
20 minutes	<u>0</u>	<u>210</u>				No Flow	<u>NO</u>		
25 minutes	<u>0</u>	<u>200</u>				Gas	<u>NO</u>		
30 minutes	<u>0</u>	<u>200</u>				Gas and Water	<u>NO</u>		
5 minute SI	<u>0</u>	<u>200</u>				Water	<u>NO</u>		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear NA Fresh NA Salty NA Sulfur NA Black NA

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

There was no flow on the Bradenhead all the way through the test

By [Signature]
Lease operator
(Position)

Witness



NMOCD Test Area: C