



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-7-2010 Operator Energex API #30-0 39-30167 ✓


Property Name Carracas 21A1 Well No. 21A1 Location: Unit 0 Section 21 Township 32N Range 05W ✓

Well Status (Shut-In or Producing) Initial PSI: Tubing 45 Intermediate Casing 105 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
5 min	0		105		
10 min	0		105		
15 min	0		105		
20 min	0		105		
25 min	0		105		
30 min	0		105		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>no</u>	
Surges	<u>no</u>	
Down to Nothing	<u>no</u>	
Nothing	<u>no</u>	
Gas	<u>no</u>	
Gas & Water	<u>no</u>	
Water	<u>no</u>	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR 0 FRESH 0 SALTY 0 SULFUR 0 BLACK 0

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: Braden head had 0 from the beginning to the end of the test

By [Signature]
Lease operator
(Position)

Witness

E-mail address