



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-8-2010 Operator Eugen API #30-0 39-30606 ✓

Property Name Carracas BB3 Well No. BB3 Location: Unit m Section 18 Township 32 Range 04W ✓

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate Casing 69 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		69		
10 min	0		69		
15 min	0		68		
20 min	0		69		
25 min	0		69		
30 min	0		69		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	No	
Surges	No	
Down to Nothing	No	
Nothing	No	
Gas	No	
Gas & Water	No	
Water	No	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR NA FRESH NA SALTY NA SULFUR NA BLACK NA

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: 0 on the Bradenhead through the hole test

By [Signature]
Lease operator
(Position)

Witness

E-mail address

