

50532/9207

Benson-Montin-Greer

03 37 34 p.m. 07-20-2010

1/1



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/oed/District/1133dmtro.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/22/10 Operator Benson Montin Greer API #30-0 39-82250Property Name EPCMU Well No. 13 Location: Unit F Section 30 Township 27N Range 1EWell Status (Shut-In or Producing) Initial PSI: Tubing 42 Intermediate 44 Casing 31 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

Steady Flow

Surges

Down to Nothing

Nothing X

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD INTERMEDIATE

REMARKS:

By Ben L. GoffWitness

(Position)

E-mail address 