

5053279207

Benson-Montlin-Greor

03 37 34 p.m

07-20-2010

1/1



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6170 FAX: (505) 334-6170
<http://emnr.state.nm.us/oand/or/district/1113346170.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/22/10 Operator Benson Montlin Greor API #30-0 39-82251Property Name EPCMU Well No. 28 Location: Unit D Section 9 Township 26N Range 1EWell Status (Shut-In or Producing) Initial PSI: Tubing 84 Intermediate 11A Casing 28 Bradenhead D

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min						Steady Flow	
10 min						Surges	
15 min						Down to Nothing	
20 min						Nothing <u>h</u>	
25 min						Gas	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD _____

INTERMEDIATE _____

REMARKS:

By Bent L. Gray

Witness _____

(Position)

E-mail address _____

