



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distr.htm](http://emnrd.state.nm.us/ocd/District%20III/3distr.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-27-10 Operator Elm Ridge Exploration API # 30-043-20644


Property Name Jicarilla 393 B Well No. 1 Location: Unit 0 Section 21 Township 23 Range 4

Well Status (Shut-In or Producing) Initial PSI: Tubing NA Intermediate NA Casing 80 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

Shut well IN For 24 Hr - Nothing on BRADENHEAD

By Ronald Graves - [Signature] Witness _____

Pumper
(Position)

E-mail address _____