

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/



(Submit 2 copies to above address)

(Submit 2 copies to above address)										
Date of Test	5/20	5/70/7010 Operator		Energen Resources				API#	300	3906220
Property Nam	ie	JICARILLA 120 C 13		Location: Unit I Section 3			Section 32 T	ownship	26	Range 4
		(Well Name	and Number)							
Pressure (Sh	ut-in or Proc	ducing)	Tubing _	95	Interme	diate	Casing _/	<u>05</u> Bra	adenh	ead <u>0</u>
OPEN	N BRADENH	EAD AND	INTERMEDIA	TE TO	ATMOSI	PHERE IND	IVIDUALLY FOR	15 MINU	TES E	ACH
	Bradenhead			Intermediate				Braden	head	Intermediate
Time	BH Blowdown	Casing Monitor	Intermediate Monitor		ermediate lowdown	Casing Monitor		Flow		Flowed
5 minutes	0		HIOTHEO		OWGOWII	Wollitor	Steady Flow			
10 minutes	0	105		—			Surges			
15 minutes	0	105	· · · · · · · · · · · · · · · · · · ·	—		<u> </u>	Down to Nothing			
20 minutes		1,03				<u> </u>	No Flow		,	
25 minutes						<u>. </u>	Gas			
30 minutes							Gas and Water			
5 minute SI	U	105	<u> </u>				Water			
If bradenhe Clear 5 Minute Si	F	vater, che resh _ radenhea	eck all of the d	ity _	nediat	t apply bel Sulfur		ack		_
						·				
			-				, д			
		,,			· · · · · · · · · · · · · · · · · · ·					
Ву	Erik 1	2etago	Eich P.	esoy	Wi	tness				
	ease 0	perati	5~		_					
		(Position								