



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/19/2010 Operator Energen Resources API # 3003906228

Property Name JICARILLA 107 2 Location: Unit K Section 33 Township 26 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) 125 Tubing Intermediate 195 Casing 195 Bradenhead 16

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	12	195				Steady Flow		
10 minutes	4	195				Surges		
15 minutes	0	195				Down to Nothing	✓	
20 minutes	0	195				No Flow		
25 minutes	0	195				Gas	✓	
30 minutes	0	195				Gas and Water		
5 minute SI	0	195				Water		


If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate _____

REMARKS:

Braden Head down to nothing after 20 mins.



By Erik Pelago Erik Pelago Witness _____
Lease Operator
(Position)