

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	5/20/2010	Operator	Energen Resources	API #	3003906378
--------------	-----------	----------	-------------------	-------	------------

Property Name JICARILLA 110 1 **Location:** Unit K Section 20 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 102 Intermediate Casing 153 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0	153				Steady Flow		
10 minutes	0	153				Surges		
15 minutes	0	153				Down to Nothing		
20 minutes						No Flow	✓	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	0	152				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediat _____

REMARKS:

By Erik Petago Erik Petago. Witness _____
Lease Operator

 (Position)