

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

				•		•		- ,	
Date of Test	5/21	5 71 7010 Operator			Energen Resources			3003906380	
Property Name	e	JICARILLA F 4			Location: Unit J Section 21		ownship 26	Range 5	
		(Well Name	and Number)						
Pressure (Shu	ıt-in or Pro	ducing)	Tubing _	105 Interme	ediate	Casing <u></u>	거 Bradent	nead <u>0</u>	
OPEN	BRADENH	EAD AND	INTERMEDIA	ATE TO ATMOS	PHERE IND	IVIDUALLY FOR	15 MINUTES E	ACH	
	E	Bradenhead			diate		Bradonhoad	Intermediate	
Time	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed	
5 minutes	0	144				Steady Flow			
10 minutes	0	144				Surges			
15 minutes	0	144				Down to Nothing			
20 minutes						No Flow			
25 minutes						Gas			
30 minutes						Gas and Water			
5 minute SI	0	144				Water	·		
<u>if bradenhe</u>	ad flowed v	vater, che	ck all of the d	descriptions tha	it apply bel	ow:			
Clear	F	resh _	Sa	alty	Sulfur	Bla	ack		
			$ \wedge $				20031 REC	123456	
5 Minute Sh	ut-in B	radenhead		Intermediat			/c/ H(-(CEIVED	
REMARKS:							UC 582	N 2010	
							VS DIL COL	IS. DIV. DIST. 3	
							C DIL COL	02013117319	
ву{	Exik (Petaro	2.1 C	Ofan W	tness				
-, <u> </u>	1 04 - 1)	Eich f						
	Huse L								
		(Position	1)						