

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	5/21	5/21/2010 Operator			Energen Resources				3003906455	
Property Nam	e	JICARILLA F 10 (Well Name and Number)				Location: Unit M Section 15			26	Range 5
Pressure (Sh	ut-in or Pro	and the same of th	·	50	Interme	diate	Casing	60 E	radenh	nead <u>0</u>
OPEN	I BRADENH	EAD AND	INTERMEDIA	TE TO	ATMOSI	PHERE IND	IVIDUALLY FOR	15 MINU	JTES E	ACH
	E	Bradenhead			Interme	diate		Brade	nhead	Intermediate
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	, ,	ermediate owdown	Casing Monitor			wed	Flowed
5 minutes	6	60					Steady Flow			
10 minutes	0	60					Surges) 		
15 minutes	0	60					Down to Nothing	1		
20 minutes		VO					No Flow			
25 minutes				—			Gas	3		
30 minutes							Gas and Water	-		
5 minute SI	0	60					Water	ſ		
If bradenhe		vater, che	ck all of the d		ions tha	t apply bel		ack _		_
5 Minute Sh	n ut-in B	radenhea	<u> </u>	Intern	nediat					
REMARKS:			•							
										
	·									
							···········	· · · · · · · · · · · · · · · · · · ·	·	
By	rik Pe	tago	Eil Re	tag.	Wi	tness				
	ease !	Operat	tor							
		(Position								