



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/21/2010 Operator Energen Resources API # 3003906501

Property Name JICARILLA F 14 Location: Unit G Section 16 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 10 Intermediate Casing 68 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0					Steady Flow	
10 minutes	0					Surges	
15 minutes	0					Down to Nothing	
20 minutes						No Flow	
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI	0					Water	


If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead Intermediate

REMARKS:

Slim hole



By Erik Petago Erik Petago Witness
Lease Operator
(Position)