



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/20/2010 Operator Energen Resources API # 3003906507

Property Name JICARILLA 110 15 Location: Unit E Section 17 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 95 Intermediate Casing 130 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	130				Steady Flow	
10 minutes	0	130				Surges	
15 minutes	0	130				Down to Nothing	
20 minutes						No Flow	✓
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI	0	130				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediat

REMARKS:



By Erik Putago Erik Putago Witness
Lease Operator
(Position)