



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/20/10 Operator Energen Resources API # 3003906659

Property Name JICARILLA 96 7 Location: Unit M Section 1 Township 26 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing _____ Intermediate _____ Casing 97 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	97				Steady Flow	
10 minutes	0	101				Surges	
15 minutes	0	103				Down to Nothing	✓
20 minutes	0	103				No Flow	
25 minutes	0	103				Gas	✓
30 minutes	0	103				Gas and Water	
5 minute SI	0	103				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear ☒ Fresh ☐ Salty ☐ Sulfur ☐ Black ☐

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

B. h. valve shut in May 14th.
After 5 minutes of shut in on B.H. only puff of
gm. too small to measure pressure.

By Ed. Edwards Witness _____
lease operator
(Position)

