



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/19/10 Operator Energen Resources API # 3003906790

Property Name JICARILLA 95 6 Location: Unit M Section 36 Township 27 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 99 Intermediate N/A Casing 105 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	105				Steady Flow	
10 minutes	0	105				Surges	
15 minutes	0	105				Down to Nothing	✓
20 minutes						No Flow	
25 minutes						Gas	✓
30 minutes						Gas and Water	
5 minute SI	0	105				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

B.H. valve shut-in May 14th

By G.D. Edwards

Witness

lease operator

(Position)

