



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/6/10 Operator Energen Resources API # 30-03907762

Property Name San Juan 30-4 Well No. 10 Location: Unit F Section 27 Township 30 Range 4

Well Status (Shut-In or Producing) Tubing 195 Intermediate N/A Casing 200 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>No Blw</u>	<u>N/A</u>	<u>205</u>	Steady Flow	
10 minutes	<u>No Blw</u>	<u>N/A</u>	<u>210</u>	Surges	
15 minutes	<u>No Blw</u>	<u>N/A</u>	<u>215</u>	Down to Nothing	
20 minutes				Nothing <u>X</u>	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	


If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

bradenhead Had Nothing!



By Don Dab
Pumper
(Position)

Witness _____

E-mail address _____