



**NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
http://www.emnrd.state.nm.us/ocd/

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 5-17-2010 Operator Energen Resources API # 3003922198

Property Name HUGHES FEDERAL COM 1 Location: Unit 0 Section 7 Township 24 Range 3  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 165 Intermediate \_\_\_\_\_ Casing 120 Bradenhead 0

**OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH**

Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes	0	120										
10 minutes	0	120										
15 minutes	0	120										
20 minutes									X			
25 minutes												
30 minutes												
5 minute SI	0	120										

**If bradenhead flowed water, check all of the descriptions that apply below:**

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_

5 Minute Shut-in Bradenhead 0 Intermediate \_\_\_\_\_

REMARKS: No Pressure on Bradenhead



By [Signature]  
Lease Operator  
(Position)

Witness \_\_\_\_\_