



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/20/2010 Operator Energen Resources API # 3003922559

Property Name JICARILLA 123 C 31 Location: Unit D Section 7 Township 25 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 500 Intermediate Casing 580 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0	580				Steady Flow		
10 minutes	0	580				Surges		
15 minutes	0	580				Down to Nothing		
20 minutes						No Flow	✓	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	0	580				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

By Erik Putago Erik Putago Witness _____
Lease Operator
(Position)

