



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/20/2010 Operator Energien Resources API # 3003922971

Property Name JICARILLA 123 C 32 Location: Unit K Section 6 Township 25 Range 4  
(Well Name and Number)

Pressure (~~Shut-in or~~ Producing) Tubing 300 Intermediate        Casing 220 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0	220				Steady Flow		
10 minutes	0	220				Surges		
15 minutes	0	220				Down to Nothing		
20 minutes						No Flow	✓	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	0	220				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear        Fresh        Salty        Sulfur        Black       

5 Minute Shut-in Bradenhead 0 Intermediate       

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Erik Retago Erik Retago Witness \_\_\_\_\_  
Lease Operator  
(Position)

