



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-20-10 Operator Elm Ridge Exploration API # 30-039-23212


Property Name Jicarilla 362 G0 Well No. 3 Location: Unit A Section 8 Township 23 Range 4

Well Status (Shut-In or Producing) Initial PSI: Tubing 53 Intermediate NA Casing 58 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

Shut well in for 24 Hr. Nothing on BRADENHEAD

By Ronald Graves - R/G

Witness _____

Pumper
(Position)

E-mail address _____