

5053279207

Benson-Montin-Greer

03 37 34 p m. 07-20-2010

1/1



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-8178 FAX: (505) 334-8170
<http://omnr.d.state.nm.us/oandd/District/1000rbras.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/21/10 Operator Benson Montin Greer API #30-0 39-23409

Property Name Full Sail Well No. 1 Location: Unit 0 Section 29 Township 25N Range 26W

Well Status (Shut-In or Producing) Initial PSI: Tubing 32 Intermediate N/A Casing 32 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD _____

INTERMEDIATE _____

REMARKS:

By Ben L. Hoyle

Witness _____

(Position)

E-mail address _____

